## The Village at Indian Creek Condominium Association, Inc.

c/o Premier CAM Services, LLC P.O. Box 152047 Cape Coral, FL 33915 Office 239-217-6599 Fax 239-217-6598

## VIC Hurricane items not covered by insurance

Vendor	<u>ltem</u>	Amount
ServPro	Insurance deductible amt. (1,250 per bldg.)	10,000.00
Performance Pool Service	Addn'l chemical & pool cleanup	730.00
Sebastian	Tree & brush cleanup	6,000.00
J.J. Maint.	Replace pool pumps	3,105.00
VIC, Golf Villas I & II Irrigation Fund	Special assesmt to replace irrigation pump	287.34
J.J. Maint.	Pool repair	175.00
Sebastian	1/5 of cost to remove damaged tree	200.00
Sebastian	2/5 of cost to remove damaged tree	200.00
Florida Gutter	Replace aluminum soffit, facia, siding & gutters	21,500.00
Dock Savers	Down payment on repair of dock between bldg. 6 & 8	2,000.00
Dock Savers	Bal. of payment for repair of dock between bldg. 6 & 8	2,000.00
Sebastian	Balance of fee to remove damaged tree	600.00
JJ Best Electric	Electrical repairs at entrance, stop sign, VIC sign, in front of pool & condo bldgs., junction switch from pool equip to shed & dumpst	2,635.76 er area
Roofing Consulting Services	Evaluation of condition of the roofs by engineer	7,700.00
Expenses not paid for yet		
Replace pressure washer		500.00

Taylor Tress to grind out 2 additional stumps behind condo bldgs.		500.00
Dock Savers	repair dock behind bldg. 5	3,800.00
		61,933.10

\$ 1,821.56 per unit

For the Board of Directors,

Kyle Hubler, LCAM Premier CAM Services, LLC